## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET SECURITY INFORMATION

25X1A

COUNTRY **SUBJECT** 

East Germany

653rd Aviation Maintenance Base,

Justerbog - Damm

DATE DISTR.

REPORT NO

1 May 1953

NO. OF PAGES

25X 6A

DATE OF INFO.

ARMY

NAVY

25X1C

REQUIREMENT NO.

PLACE ACQUIRED

25X1A

REFERENCES

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE. THE APPRAISAL OF CONTENT IS TENTATIVE. (FOR KEY SEE REVERSE)



25X1X

The 653rd Aviation Maintenance Base See Encl. As was located approximately size fillometer south set Justing Denn ALAGE 1505 and E It was adjacent to and east of the Justing Bank to Dennewits 5157N-13015.

Rohrbeck 5157N-13035 and Bochow 5156N-13055. The area of the base was approximately km. wide at the northern end, 1km. wide at the southern end and 2 km. long. Located within this area were: two mechanised artillery regiments Junidentified which were subordinate to intermediate artillery division Junidentified which had approximately nine U-2 type aircraft; and the 653rd Aviation Maintenance unit. (As far as I know the designation of the maintenance unit at Justing Damm was always the 653rd Aviation Maintenance Base. This dated back to its inception in the Fall of 1945. At that time, the 653rd Aviation Maintenance Base was involved only in the repair of vehicles, trucks, and automobiles. Later on date unknown it turned to the repair of aircraft instruments and navigational and radio equipment.)

SECRET

25X1A FBI

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)
Approved For Release 2001/11/21 : CIA-RDP80-00810A000900550009-3

This maintenance base was primarily involved in the repair of all aircraft instruments (for both jet and conventional type aircraft), aircraft navigational equipment, aircraft and ground radio equipment, and listening devices. (I have heard that the PARM (Podvizhnoye Aviatsionoye Remontnoye Masterskiye) system was still being used in repairing aircraft in the Soviet Zone of Germany.) I am not certain but I assume that the source of supply was the USSR and Soviet Zone factories. Since no aircraft but the U-2's mentioned above ever used the field, I assume that the equipment was brought in for repair by truck. I can not state definitely whether this maintenance base was considered to be a major or a minor base; but I assumed it to be a major instrument repair installation, since it had been in existence since the Fall of 1945. No runways, taxiways, or hardstands of any kind were either planned or under construction at Jueterbog-Damm. There were no revetments there.

25X1X

25X1X

25X1X

25X1X

25X1X

On frequent occasions while at Jueterbog-Damm flights of twin jet aircraft, alone and in formations of three.

as the IL-28 twin jet. Wing tips of the aircraft I saw had oval objects attached.

of my memory sketch /See Enclosure A/ was a radar antenna, of which I have drawn also a memory sketch /Enclosure B/. The mast was constructed of steel and appeared to be a portable unit; about 14 m high and Hald stationary by eight guy wires. Atop the mast were four paddle-like screens which extended approximately 12 m. from the center of the mast. These screens were rectangular, approximately 12 m. long, 80 cm. - 1 m. wide, and interconnected with five or six strands of wire around the outer edges. They were constantly turning. Power lines led from the antenna to an enclosed van adjacent to the mast.

Memory Sketch of the 653rd Aviation Maintenance Base


Base Memory Sketch of Radar Antenna

Legend

Bhat where The . -- )



- Point #1 Residential Area. This area contained a few scattered, twostory stuccoed brick homes used by the local people and in no way affiliated with the military or the base.
  - #2 Building. This was an L shaped, one-story, white, stuccoed brick building approximately 50 m. long (N-S), 30 m. long (E-W), 12 m. wide, and 3 m. high with a slightly pitched grey slate roof. The building contained a kitchen Foint A, an officer and enlisted men's mess hall Foint B and an officer and enlisted men's club Foint C, also used as a theater. Pistols, carbines, and foodstuffs were stored in the cellar of the building.
  - #3 Former Bomb Shelter. This was a reinforced concrete building, earth covered, approximately 12 m. square and  $2\frac{1}{2}$  m. high which was being used to store perishable foodstuffs. It had a steel door entrance and was guarded at night by a guard armed with a carbine.
  - #4 Stable and Pig Pen. Approximately 25 m. long and 15 m. wide; this area contained a wooden stable in which were kept 3 horses and approximately 50 pigs. Ten pigs were the property of the maintenance unit and the remainder belonged to the Mechanized Artillery Regiments.
  - #5 Officer's Billet No. 2. This was a two-story, brown stucced brick building 40 m. long, 15 m. wide and 8 m. high with a slightly pitched grey slate roof.
  - #6 House. This was a two-story, brown studged brick building 15 m. square and 8 m. high with the same type roof. This house was used by the Base Commander (Maintenance Unit) and a few other officers.
  - #7 Officer's Billet No. 1. /Same as in Point 57
  - #8a Wooden Fence. This was a wooden fence two meters high and topped with barbed wire.
  - #8b Wire Fence. This wire fence was two meters high topped with barbed wire.
  - #9 Headquarters Building. This was a two story, studeded brick building 40 m. long, 15 m. wide, and 8 m. high with the same type roof. The first floor contained the offices, and the second floor was used as a barracks for the enlisted men.
  - #10 Road. This was an asphalt surfaced road approximately 10 m. wide, with sidewalks and intermittent street lights.
  - #11 Main Entrance. This was the main and only entrance to the base, and it consisted of a solid metal, blue, two section gate approximately 2½ m. high and 10 m. wide. This entrance was guarded at all times by guards (of the mechanized artillery regiments) armed with carbines. Enlisted men were restricted to the area, but officers were able to come and go as they pleased and were not requested to show any passes.
  - #12 Building. This was a one-story, wooden structure used as a garage and gun storage by the Mechanized Artillery Regiment. One section of the building /Foint 12a7 was a bathhouse constructed of brick and used only by the enlisted personnel of the 653rd Aviation Maintenance Base.



. පරිකි Annex A (con't)

#### Legend

### Point #12a Bathhouse.

- #13 Garage. This was a one-story, stuccoed brick building 15 m. long, 20 m. wide, and 4 m. high with the same type roof and metal doors. The garage was used by the 653rd Aviation Maintenance Base; they kept two ZIS type trucks, one black, light Mercedes sedan, and one Chevrolet sedan.
- #14 Living Quarters. This was a one-story, stuccoed brick building approximately 12 m. square and 5 m. high with the same type roof. This building was used by the main engineer and a few other officers.
- #15 Maintenance Workshop. This was a former hangar, constructed of metal, approximately 70 m. long, 30 m. wide, and 20 m. high with a metal, barrel shaped roof. I am unable to offer any further information, since all the workshop buildings were restricted to all except those who worked there. However, there was not any sort of security system in effect.
- #16 Workshop. This was a one-story, stuccoed brick building approximately 25 m. long, 30 m. wide, and 4 m. high with the same type roof as the houses.
- #17 Workshop. Identical with point #15.
- #18 Sportfield.
- #19 Buildings of the U-2 Squadron vunidentified7
- #20 Stone Wall. This wall was approximately 2½ m. high and 30 mm. thick. I am not certain, but I assume that this wall completely enclosed the area of the base.
- #21 Radar Antenna. \[ \sum\_{\text{See}} \text{Enclosure B} \]